
# **DE-STA-CO Series 3P Expanding Mandrels**








Expanding Mandrels – 3P



#### **Index**

Operation and Characteristics	Page 3
Standard Mandrels	Page 4
Manual and Automatic Mandrels	Page 5
Spline and Needle Mandrels	Page 6
Mandrels for Turbines and Jet Engines	Page 7
Application Examples	Page 8-9
Balancing and Threaded Mandrels	Page 10
Workholding and Flange Mandrels	Page 11-12
Using "3P" Slotted Sleeves for variable part sizes	Page 13
Workholding and Part Inspection Applications	Page 14-15





#### (1) OPERATION:

"Pressure is applied manually, hydraulically, pneumatically or mechanically against the internal hydraulic fluid (A). The metallic wall(B) expands in parallel and centers the parts to be tightened, gripped, or clamped.

#### (2) CHARACTERISTICS:

a) DIMENSIONS: 8 to 700 mm Ø; max length: 1 meter

b) **CONCENTRICITY**: (in total, measured with a comparator)

> 6 to 50 Ø ...... 0,002 mm 51 to 100 Ø ...... 0,003 mm 101 Ø and above ...... 0,005 mm

Total expansion =  $\frac{\emptyset \times 3}{1000}$ c) EXPANSION:

Example: Expandable 20 mm Ø mandrel

Total expansion =  $\frac{20 \times 3}{1000}$  = 0,06 mm

#### d) EXPANDABLE AREA LENGTH:

#### Dependent on the parts to be adjusted:


- Manually operated mandrels: are available in extended lengths
- The expandable length of the automatic mandrels must be equal to or lower than the length of the part to be adjusted.
- To use an automatic mandrel with parts of different lengths, it is necessary to use removable stops in order to cover the area which isn't used and prevent deformations.



### Series 3P – Standard Mandrels for Precision Workholding



- Standard Products
- Manual Control of Expansion and Retraction



Manually operated mandrels use Allen keys for operation. Applications include assembly inspection, grinding and fine turning of parts.

#### MANDREL SIZING CHART

**Note:** On standard mandrels the Allen key is inserted on the left side for manual control of the mandrel expansion and retraction.

Nominal A Ø	T total length	E expandable length	Ø diameter in microns
14	135	50	40
15	145	60	42
16	160	70	45
17	160	70	51
21	130	70	63
18			50
20	130	70	56
22			62
24			67
25	130	70	70
26	130	70	72
25,4	130	70	70
27	155	80	81
28	155	80	84
30	175	95	90
32	175	90	96
35	175	90	105
40	175	100	120

#### **Mandrel Size Example:**

+0,078

20 E 8 Ø part adjustment


+0,040

- Ø 20,03 minimum Mandrel Dimension in (unloaded) Position
- Ø 20,09 maximum Mandrel Expansion (loaded)
   Concentricity 20,002 throughout length of "E" Dimension,

   Special sizes are available from 10 to 200 mm. Unless specified, the manual control of the expansion and retraction will be located on the left side
- Right side control is available and must be specified



#### **Manual Mandrels**




.....

Manual Tailstock Centering Mandrel


#### **Automatic Mandrels**




Automatic Grinding Mandrels with part positioning control and integrated sensors (4,000 parts per day).



**Automatic Mandrels** (lathe turning)



Dual expansion of automatic mandrels for ignition box




**Automatic Mandrel** (I. D. grinding)

# **Splined and Needle Mandrels**

# **Splined Mandrels**

**USE:** Turning – Grinding – Inspection – Balancing – Cutting, etc...




Grooved skirting mandrels.

Machining automotive brake discs.

Splined Mandrels are capable of 0,005 mm concentricity.


Splined expanding mandrels

are possible.











#### **Needle Mandrels**










- Ø 350-600 mm range
- 0,005 concentricity
- weight: 450 kg max.











Broaching of turbine blade components on horizontal machining Center






O.D. Grinding:



components on the CFM 56 (SNECMA) drum







The excellent centering precision and robustness of the "3P" expanding mandrels improve the quality of cutting, hobbing and grinding operations on manual or automatic machines.


DE-STA-CO's precision mandrel offering and performance delivers value by increasing your quality, productivity, and profitability.

#### **CUTTING 1 GEARBOX PINION**


Centring parts by hydraulic fluid at 40 bars, using a rotary seal. Parts on the I.D. surface are secured via the machine cylinder.

#### **CUTTING 2 GEARBOX PINION**

Centering and holding parts via the initial mandrel expansion - Holding the parts on the I.D.



Cutting 2




#### **CUTTING 3 GEAR BLANKS**

Centring parts via the mandrel expansion – Holding the parts on the I.D.

Part height compensated by Belleville washers inside the "3 P".

#### **CUTTING 4 GEAR BLANKS**


Centering parts using hydraulic fluid at 50 bars through the I.D. centre – Tightening the parts on the I.D. via the machine cylinder.




www.destaco.com

**Automotive Workholding** 






**Cutting Gears** 




Cutting with a "LORENZ" Gear Hobbing machine







# **Balancing and Threaded Mandrels**



#### **Threaded Mandrels**




Requires several threaded inserts in order to cover tolerance.



Example: On a B 14 Ø Mandrel, ring nuts can be used from M 18 to M 24.





#### Holding two similar part diameters separated by a gap.






Simultaneous clamp and release of several parts.






Control of two or several different part diameters.






Manual O.D. Mandrel. **Application: Constant monitoring** of jet engine components being assembled.




# Flanged Mandrels used for accurate stop location






# **Workholding and Flange Mandrels**

### Mandrels used on tail stock for lathes




### **Gear Hobbing Mandrels**



Manual on/off expansion/retraction of part

# Hydraulic O.D. mandrel with pressure gange and manual on/off clamp/unclamp function





# Using 3P Slotted sleeves for variable part sizes




On a basic "3 P" mandrel, one or several expandable clip sets can be fitted and used in order to hold parts of different diameters. Precision workholding tolerances of (2 microns).













# **Workholding and Part Inspection Applications**


# **Aerospace Tooling** Centering-clamping of the I.D. designed into workholding fixture




# **Cutting – Parallel Grinding Inspection**




# **Inspection of Pinions**







# **Part Centering**



If your part tolerances are higher than our Mandrels shown, please contact us for application assistance using our

MECHANICAL EXPANDABLE SLEEVE MANDRELS.





